**Gaston County Building Inspections Department** 

Phone (704)866-3155 Address: 128 W Main Ave, Gastonia, NC 28052

**Case Number:** COD-H-25-03-11-00458

**Inspection Date:** Fri Jul 18, 2025

**Inspector:** 980-421-7543, Chris Harkey

Case Module: Code Case Inspection Status: In Violation

Inspection Type: Zoning Complaint Follow Up

Inspection

Job Address: 3014 BIRCHFIELD LN

GASTONIA, NC, 28056

Parcel Number: 309450

Contact Type Company Name Name

- -

Checklist Item Status

Door is not weathertight Failed

Structural cracks allowing rodents Failed

Ventilation inadequate Failed

House numbers required Failed

No privacy door Failed

Holes in walls Failed

General Comments - General Comments Failed

Jul 18, 2025 Page (1)

Checklist Item	Status
Floor is weak	Failed
Floor covering must be repaired	Failed
Floor is weak	Failed
Exposed wiring	Failed
Windows are not weathertight	Failed
Windows are not weathertight	Failed
Repair/replace above ground storage tanks	Failed
Outlets not covered	Failed
Step / deck conditions maintained in safe manner	Failed
Ventilation inadequate	Failed
Lighting inadequate/inoperable	Failed

Jul 18, 2025 Page (2)

Checklist Item Pipes not properly insulated	<b>Status</b> Failed
Water not draining away from dwelling	Failed
Idv 24-55g cont; water/pest tight on rack/rollout	Failed
Holes to admit rodents	Failed
Exhaust fan inoperable	Failed
Repair broken/burst/frozen plumbing pipe/fixture	Failed
Light sockets broken/inadequate	Failed
Floor covering must be repaired	Failed
Inadequate facility for egress in case of fire	Failed
Leaky faucet	Failed
Holes in ceiling	Failed
Repair/replace/install heating equipment	Failed

Jul 18, 2025 Page (3)

Checklist Item	Status
Floor is not impervious to water	Failed
Water supply = adequate / meets regulations	Failed
Leaking plumbing	Failed
Furnished applicances inoperable	Failed
Door needs repair	Failed
Lighting inadequate/inoperable	Failed
Windows do not have screens	Failed
Tall grass more than 12" in height	Failed
MHP owner responsible for trash removal	Failed
Condition of wiring/systems inadequate	Failed
Interior walls/celings not finished	Failed

Jul 18, 2025 Page (4)

Checklist Item MHP owner responsible for pest infestations	<b>Status</b> Failed
Recepticles do not have covers	Failed
Central/Electric systems inoperable	Failed
Lighting inadequate/inoperable	Failed
Sewage-meets regulations 1 home/connection	Failed
Holes in ceiling	Failed
Holes in ceilings	Failed
Rubbish/garbage not picked up	Failed
Repair any exposed or unsafe electrical wiring	Failed
Bug infestation	Failed
Exposed wiring	Failed
Cracked window glass	Failed

Jul 18, 2025 Page (5)

Checklist Item	Status
Electric/Phone/Cable-ind home connections & UG	Failed
Habitable rooms (minimum 1 window)	Failed
Bathroom/water closets (ventilation system/window)	Failed
Space#s/3" tall/contrast color near ent & int rd	Failed
Windows do not have screens	Failed
Steps missing/needing repair	Failed
Windows do not have screens	Failed
No handrails when 4+ risers - No handrails when 4+ risers	Failed
General (minimum 1 window)	Failed
No/broken smoke detector (120v hardwired)	Failed
Holes in walls	Failed

Jul 18, 2025 Page (6)

Checklist Item Electrical hook-up violations	Status Failed
Door does not have screen	Failed
Windows are not weathertight	Failed
Floor around plumbing delapidated	Failed
Cracked window glass	Failed
Insufficiant lighting	Failed
Grounds/buildings areas properly maintained	Failed
Structural integrity	Failed
Porch needs repairing - Porch needs repairing	Failed
Pipes not properly insulated	Failed
No guardrail when 30+ inches above grade - No guardrail when 30+ inches above grade	Failed
Cracked window glass	Failed

Jul 18, 2025 Page (7)

Checklist Item	Status
Floor covering needs repair	Failed
Recepticles do not have covers	Failed
Exposed wiring	Failed
Repair/replace unsafe/dangerous cooking appliances	Failed
Other systems/portable heating primary heat source	Failed
No trash/litter/debris/weeds/sewage	Failed
Lock is inoperable	Failed
Recepticles do not have covers	Failed
Floor is weak	Failed
Holes in walls	Failed
Convenience recepticle broken/inadequate	Failed

980-421-7543, Chris Harkey































































































